Room #

air compressor room

East Wall

South Wall

MC Secure Storage

South Wall Continued

West Wall

Cat Walk

**General Comments** 

Item & Location

Cooling pits 2 and 5 missing a lid prop

Exhaust for ACCU needs a bird screen

clean around grounding circles

clean grates and bolt down

clean aircraft cooling box lids and AFFF red sprayers

need conduit for blue wire on mullions/west/east frame of Mega Doors

need sign for air compressor room

air compressor hoses not connected on NE corner of unit

clean in air compressor room

tank needs to be cleaned and painted

repaint doors

touch up paint and clean catwalk ladder

paint conduit next to catwalk

touch up paint on conduits

provide label for BGSE box

finish painting conduit

clean off top of panels

clean off overspray on fire conduit

clean rust off door closer on East Esit Door (clean door)

label Schneider Electric box

open conduit hole on top of panel "LP1EA 100A 120/208V 2PH 4@ FED FROM LP1E"

clean tops of boxes

AFFF pull station open and not secured

Remove carboard from top of conduit

paint/seal base wall behind eye wash station

open holes in rated wall need to be filled

paint conduit/remove overspray

**HVAC** shutdown button losing letters

remove pull string on cut-off switch

paint adviation ordnance door

clean windows - paint wall above Av. Ord. window

touch up paint everywhere

exposed wire for MC Secure Storage

repair Caulk next to MC secure storage

no conduit between boxes above eye wash station next to avionics

correct misspelled sign sign name for Ordnance

Caulk/fill in pass through conduits

cracks in block wall - south wall

seal grates on west wall

paint/clean

fire plates on door frame are painted over - remove paint - check all fire rated doors for issue repair all control joints

repair air control joints

remove excess all thread for 400Hz converter stands

crack in block wall in between windows of main control room remove cover on boxes for A/C unit open doors for 400Hz converter in front of control room - close doors repair dent on frame to AFFF room - repaint seal conduit above eye wash station next to AFFF room remove extra conduit hangars

loose fire speaker in between Power Line and Air Frame Shop

fill in 8 holes after pipe was moved near Air Frame Shop (pipe goes up length of South Wall)

compressed air line needs to be labeled every so often (check all compressed air lines)

Air compressor hose not fitted - far west reel

repair belt in exhaust fan

missing bolt for catwalk ladder to attach ladder to wall

lot of light bulbs out in ceiling

bolts in MegaDoor need to be tightened along length of door

Mullion pit cover plate needs to lay flat so it is not a trip hazard

grate L bracket is too low - creating a trip hazard

remove grass in paint and re-paint along north floor in Bay 3

clean bars in MegaDoor

mullion wires need to be in conduit

mullion conduit need to be painted

seal gaps between floor and ACCU boxes/grates

limit switch cable too much slack - secure excess cable properly

remove all FOD from walkway

heat shield dinged - North Row - East Side crane beam needs to be touched up with paint back side of conduits not painted natural gas labels need to be put on pipe remove construction debris from top of Air Compressor Room label all electrical panels - inside and out paint expansion joint block on south east wall address gaps in metal beam running along south wall clear overspray off everything all sprinkler heads still have covers on them all strobes need to say alert, not fire all control joints need to be repaired (coming undone) install heat shields on crane install fall protection along north side of corridor caulk door frames on west wall

Drips on translucent wall panels on exterior of building scratch on fascia on extgerior of building

Thomas Marks Comments

adjust exhaust fan belts

AFFF trench grates - no bolts

masking paper and tape throughout

support fabric door strobe conduit east end

foam start switches disassembled

label all piping

joint at hangar and admin

caulk door jamb at flor east

open penetration sleeves above eyewash east

wier/string at disconnect for mitsubishi split unit

separation of caulk at control joint behind east transformer

eye wash/shower alarm switches inconsistent

wires at avionices secure room door - card reader

cut jamb for hardware

paint conduits

seal HVAC vents, sprinkler pens

open J boxes

structural cracks

misc open penetrations

caulk joint at partition and G-line wall

painted over jamb/door fire rating label

FA/flame Eye J boxes - conduit between boxes

transformer supports - cut all threads off below

eyewash/shower valve #60 partially closed

masking on CRAC unit disconnect

caulk/point G-line at 2nd deck intersection

gap in flashing at top of G-line wall

cut off strapping above foam room door

fire main at G-line penetration - fix escutcheon plate

masking on FA conduit above foam room door

sprinkler heads covered with foil

unused penetration behind fire main on G-line wall

masking on column at ceiling W of foam room door

fire sprinkler elbow at ceiling not painted

2 unused unistruts above lobby doors

foam blocks at ceiling above 2nd transformer from W wall

heat shrouds on cranes not installed

fabric door W panel - bonding wire at lift motor - P 101-0059

compressed air coil in ceiling, W wall

ceiling lights inoperable

astragal/mullion for fabric door - trap doors are trip hazards

tape and operspray on translucent panels

W catwalk ladder mounting bolts

cable from catwalk

J box cover missing - NW corner at 14'

Mullion lift motor limit switch wiring is excessive length and not secured - P 53,57,58

FA conduit coupler broke above main door in fabric door - P 101-0062

catwalk grating not properly secured - P 101-0061

trash and debris in grating on catwalk - P 101-0056, 101-0060

trash on air compressor room roof